

KIRA TECH TIP

Change Keep Relay

Set PWE = 1

Mode MDI

<System><PMC><PMCPRM><Keeprl>

Cursor to keep relay bit

<1or0><Input>

Set PWW=0